



On page 11 of the test report VFIBW95119805 Test report-Rev1 PDF. The channel 37 30MHz -1GHz table need to be corrected.

[We have corrected the table date of page 11. The Amendment report has been uploaded to web site.](#)