SIEMENS

March 21, 2017

Nemko Canada Inc. 303 River Road Ottawa, Ontario, Canada K1V 1H2

To whom it may concern:

Re: Siemens Canada Limited Cover Letter

We, Siemens Canada Limited, confirm that the original SPORTON DFS Report No.: FZ4O0971 Dec 19, 2014 for FCC ID: Z64-WL18DBMOD, IC: 451I-WL18DBMOD accurately represents the test results under the new conditions in FCC ID: VG5RX1400, IC: 4997A-VG5RX1400.

No modifications were made to the Texas Instruments product with FCC ID: Z64-WL18DBMOD, IC: 451I-WL18DBMOD. It was used "as is" in our RX1400 product with the FCC ID: VG5RX1400, IC: 4997A-VG5RX1400.

Sincerely,

3/21/2017

X Ma

Signed by: LEW NORMAN

Norman Lew

Senior Certification Engineer Tel.: 905-482-7217 Email: norman.lew@siemens.com

Siemens Canada Limited / Limitée

300 Applewood Crescent Concord, Ontario L4K 5C7 Canada

Telephone: +1 (905) 856-5288 Fax : +1 (905) 856-1995 www.siemens.com/ruggedcom