

# FCC Label Format&Location:

## SIZE:160X80mm

<p><b>Midea</b> MICROWAVE OVEN (HOUSEHOLD)</p> <p>MODEL NO.: EM245A5L-PV SUFFIX A MANUFACTURED: January, 2014 POWER INPUT 120V a.c 60Hz 1350W, SINGLE PHASE WITH GROUNDING, OUTPUT FREQUENCY 2450 MHz. THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J.</p> <p>FCC ID:VG8XM245AYY-PV</p> <p>MADE IN CHINA</p> <p></p>	<p><b>CAUTION</b> •THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.</p> <p><b>WARNING</b> •DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH-VOLTAGE POTENTIALS.</p> <ul style="list-style-type: none"><li>• TO ENSURE CONTINUED PROTECTION AGAINST SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.</li><li>• CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRICAL SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, TURNTABLE MOTOR, LOW VOLTAGE TRANSFORMER (TOUCH CONTROL TYPE), TIMER &amp; TIMER MOUNTING BRACKET (MECHANICAL TYPE).</li><li>• NOT FOR BUILT-IN INSTALLATION.</li><li>• RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.</li></ul> <p>PN: 2618312*****</p>
---	---

Label location

