



FCC Label:

认证标志，不同认证机构的不一样
需要按实际认证标志替换

<p>TOSHIBA MICROWAVE OVEN MODEL: EM9P022XC POWER SUPPLY:120V~ 60Hz RATED INPUT(MICROWAVE):1400W E214180 RATED OUTPUT(MICROWAVE):900W MICROWAVE OUTPUT FREQUENCY:2450MHz MANUFACTURE DATE:MM.YYYY FCC ID: VG8XM9P02YY HOUSEHOLD USE ONLY (NOT FOR COMMERCIAL USE) THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J. MADE IN CHINA Guangdong Midea Kitchen Appliances Manufacturing Co.,Ltd. No.6,Yong An Road,Beijiao,Shunde,Foshan.</p> <p> LISTED 54NJ E214180</p> <p> WARNING:Cancer and Reproductive Harm-www.p65warnings.ca.gov</p>	<p>CAUTION·THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.</p> <p>WARNING· TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTERCASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS.</p> <p>· CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING.SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNTABLE MOTOR, DAMPER MOTOR,L.V. TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE).</p> <p>· RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.</p> <p>·NOT FOR BUILT-IN INSTALLATION.</p> <p>CAUTION – Hot</p>
--	--

日期号: MM.YYYY

举例: July.2021

规则: 英文月份全称+年份4位

月份汇总参考:

一月: January

二月: February

三月: March

四月: April

五月: May

六月: June

七月: July

八月: August

九月: September

十月: October

十一月: November

十二月: December

FCC Label Location:

