




Test report No. : 4789400505A-US-R1-V0
Page : 141 of 142
Issued date : Nov. 27, 2020
FCC ID : VGY2865

802.11ac (VHT80)



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789400505A-US-R1-V0
Page : 142 of 142
Issued date : Nov. 27, 2020
FCC ID : VGY2865

Co-Location Mode

802.11n (HT20) +802.11a



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan
Telephone : +886-2-7737-3000
Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0