



9/16/2020

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

SUBJECT: Change of ID

To Whom It May Concern:

This letter grants authorization for representative of Masimo to apply to the FCC for a change in identification as specified under 47CFR section 2.933 of the FCC rules.

The original certification FCC ID TFB-1004 will remain valid.

This authorization applies to the Laird model Sterling LWB5, FCC ID TFB-1004. The original grant date was 06/07/2017

Masimo will be marketing the Sterling LWB5 module as a product under a new FCC Identifier. Masimo's grantee code is VFK and proposes that it be issued FCC Identifier VFK-IRISA1 for the module.

Laird has no control or responsibility with regards to the installation and use of the VFK-IRISA1 module in the products outlined by Masimo. As a result, Masimo takes ownership and responsibility for compliance of their products which include the VFK-IRISA1 module.

The original test results, technical information and relevant documents continue to be representative of and applicable to the changed equipment. Any confidential information regarding the TFB-1004 module shared to various test and certification firms shall remain confidential amongst the parties involved and not be shared to other third parties (including Masimo) unless authorized.

Sincerely,

A handwritten signature in black ink, appearing to read "Ryan Urness", written over a light blue horizontal line.

Ryan Urness  
Director of Test Services  
Laird Connectivity