



ROGERS LABS, INC.

4405 West 259th Terrace
Louisburg, KS 66053
Phone / Fax (913) 837-3214

April 19, 2012

Timco Engineering Inc.
849 NW State Road 45
Newberry, FL 32669

Federal Communications Commission
Equipment Approval Services
P.O. Box 35815
Pittsburgh, PA 15251-3315

Applicant: DBII LTD
16F-3, 482 Zhongxiao East Rd, Sec 5
Taipei 11083 Taiwan

Re: Attestation letter, Test Report correction FCC ID: VKV-F52N

Type errors were recently discovered in the submitted test report for the VKV-F52N application. As such the errors have been corrected and incorporated in the attached report (file: DBii F52N Pro 110711 15c TstRpt 120410r3.pdf). Errors were found in the reported Power Spectral Density plots and data submitted for this application. The data has been corrected and revised report created (file: Dbii F52N Pro 110711 15c TstRpt 120410r3.pdf). Corrected Power Spectral Density plot includes #58, 59, 60, 117, 118, and 119 found on pages 52-53 and 82-83, and corrected data recorded in tables on pages 89 and 91.

No modification or correction to Grant of certification is required due to these corrections.

Please place this revised report on file.

Should you require any further information, please contact the undersigned.

Thank you for your consideration in this matter.

Sincerely,

Scot Rogers
Rogers Labs, Inc.
Enclosures