



Appendix C

Date: 2013-08-16
Report No.: 60.870.13.028.01F
Model No.: BLINK1.1



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-08-16
Report No.: 60.870.13.028.01F
Model No.: BLINK1.1



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-08-16
Report No.: 60.870.13.028.01F
Model No.: BLINK1.1



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-08-16
Report No.: 60.870.13.028.01F
Model No.: BLINK1.1



Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-08-16
Report No.: 60.870.13.028.01F
Model No.: BLINK1.1

Photo of EUT – Internal EUT Photos



Appendix C

Date: 2013-08-16
Report No.: 60.870.13.028.01F
Model No.: BLINK1.1

Photo of EUT – Internal EUT Photos

