


INTERTEK TESTING SERVICES

Internal photos

Handset Unit assembly




Handset Unit Main PCB comp side




INTERTEK TESTING SERVICES

Internal photos

Handset Unit Main PCB solder side



Dect Antenna




DCX79 Dect RF module, All the RF part was disabled by software

INTERTEK TESTING SERVICES

Internal photos


Wifi Antenna




INTERTEK TESTING SERVICES

Internal photos

DAM front side



DAM rear side




DCX79 Dect RF module, All the RF part was disabled by software

INTERTEK TESTING SERVICES

Internal photos


Base Unit Oscillator PCB comp side




INTERTEK TESTING SERVICES

Internal photos

Base Unit Oscillator PCB comp side




Charger Unit Main PCB comp side (View 1)




INTERTEK TESTING SERVICES

Internal photos

Charger Unit Main PCB comp side (View 2)




Charger Unit Main PCB comp side (View 3)




INTERTEK TESTING SERVICES

Internal photos

Charger Unit Main PCB display side (View 1)



Charger Unit PCB display side (View 2)



INTERTEK TESTING SERVICES

Internal photos

Charger Unit PCB display side (View 3)

