



## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Mode: Transmission

MBP161TIMERPU  
Radiated Emission –Parent Unit



Front View



Rear View


---

FCC ID: VLJ-MBP160PU  
IC: 4522A-MBP160PU


**INTERTEK TESTING SERVICES**

**The Worst Case Configuration Photographs – Mode: Transmission**

MBP160PU  
Radiated Emission – Parent Unit



Front View



Rear View

---

FCC ID: VLJ-MBP160PU  
IC: 4522A-MBP160PU

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Mode: Sound Receiving Mode

MBP161TIMERPU




FCC ID: VLJ-MBP160PU  
IC: 4522A-MBP160PU

## INTERTEK TESTING SERVICES

---

### The Worst Case Configuration Photographs – Mode: Sound Receiving Mode

MBP161TIMERPU



## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Mode: Sound Receiving Mode

MBP160PU



FCC ID: VLJ-MBP160PU  
IC: 4522A-MBP160PU

## INTERTEK TESTING SERVICES

---

### The Worst Case Configuration Photographs – Mode: Sound Receiving Mode

MBP160PU

