

Dear Mandy,

Bill told me to contact you for this, kindly allow me to explain:

Back in time we uploaded a label with a wrong FCC ID under this tracker, TLCT532.

Meanwhile the grantee has sold this device with wrong label on it.

I explained the situation to the FCC people by KDB inquiry, see attached document KDB245147.pdf

As result of this discussion, the FCC has already put the original filing with FCC ID: VQ7TM10-B-QQ (that contains the wrong label) in TCB AUDIT mode, so that we will be able to add the attached updated label and the explanatory letter. So we need to add two exhibits here.

Can you help to put these two exhibits in this closed tracker?

Once done (as you can read in the KDB discussion) we "change ID" this FCC ID to the shorter FCC ID: VQ7TM-B-QQ which job I already have uploaded in the new tracker TLCT1366.

Best Regards,

Mark

-----Original Message-----

From: William Graff <William_Graff@micomlabs.com>

To: Mark Email. Koop <mark.koop@teleconformity.com>

Subject: RE: Label issue with tracker TLCT532

Date: Tue, 16 Sep 2014 18:07:12 +0200

Mark,

The easiest is simply not to involve FCC at all. There are two scenarios which come to mind: (1.) we create a brand new filing with the new ID, or (2.) we file a Change of ID pointing back to the original filing. The first option is cleaner but requires a little more work. The second option has slightly more risk since it is based upon an incorrectly identified device, but in the long run it may not matter – if caught we can simply feign ignorance and promise not to do it again.

What do you want to do?

Bill

From: mark.koop [mailto:mark.koop@teleconformity.com]

Sent: Tuesday, September 16, 2014 1:00 AM

To: William Graff

Subject: Label issue with tracker TLCT532

Bill,

This client came back and had noticed that the FCC ID on the uploaded label is not the same as the FCC ID from the filing itself. The FCC ID from the filing is VQ7TM10-B-QQ but the label misses the "10" in between, see attached screen-shot of the label below. I was thinking this can be done either in audit mode, or maybe by a class2 change. However with class2 change the original entry will still contain the wrong label. What would you advise?

BR.,

Mark



-----Original Message-----

From: micomlabs_certification@micomlabs.com
To: mark.koop@teleconformity.com
Cc: william_graff@micomlabs.com
Subject: MCMS - TLCT532 - FCC Original Grant - CERTIFICATION WIP > AWAITING CLIENT APPROVAL
Date: Fri, 22 Feb 2013 00:35:44 +0100



Certification Management System

Tracker: TLCT532 FCC Original Grant / RFID READER/WRITER MODULE wit FCC ID: VQ7TM10-B-QQ

Certification ID#: VQ7TM10-B-QQ

Status changed from: **CERTIFICATION WIP** to: **AWAITING CLIENT APPROVAL**

[Click here to access the system.](#)