



1132 West 1700 North  
Logan, UT 84321 USA

t.435.753.1881  
f.435.753.1896

js@junipersys.com  
www.junipersys.com

September 12, 2013

Federal Communications Commission  
Equipment Authorization Branch  
7435 Oakland Mills Road  
Columbia, MD 21046

Re: Part 2.933 Change in Identification to FCC ID: VSF23795

Dear Sir or Madam,

I hereby request a change in identification in accordance to CFR 47 Part 2.933 of the FCC rules. The original identification used on the equipment prior to this application for Change in Identification is QIPPH8-P. The date of the original grant of the equipment authorization is 10/21/2011.

I hereby certify that the equipment bearing the modified identification, FCC ID: VSF23795, does not differ from the original equipment.

I further certify that the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

Kent Campbell  
Product Assurance Engineer