

SAGEMCOM

To: Federal Communication Commission
445 12th Street, SW
Washington, DC 20554

FCC ID: VW3FAST5260CV and VW3FAST5260

To whom it may concern:

This letter is provided to address the FCC requirements from 2/8/2018 from KDB inquiry # 178993.

SAGEMCOM was not aware that the DFS bands had to be tested to meet the new requirements of Docket 13-49.

SAGEMCOM was provided with grants with note code 38 which implied that the device could be sold after the deadline of June 1, 2016. SAGEMCOM was not aware that the note code 38 on the grants was the administrative error of TCB. Based on the Grant delivery from the TCB, we, SAGEMCOM, continued to put the product on the market after the deadline.

When we were informed that DFS testing was missing per new requirements, we have planned an emergency corrective action. The tests were performed from February 14th, 2018 to February 19th, 2018. All the tests are PASS and the test report is now available.

We acknowledge that the similar issue has occurred with our second FCC ID: VW3FAST5260 which is the product of the same family as FCC ID: VW3FAST5260CV. The DFS testing performed from February 14th - 19th is applicable to both FCC IDs as the radio parts of both FCC IDs are strictly identical. So this cover letter addresses the requirements for both FCC IDs.

SAGEMCOM is also aware of the changes being made on the previous grants by the TCB. The changes are requested by TCB to update the note code 38.

Please feel free to contact us if you have any other questions.

Sincerely,



Jacques LE ROUX
R&D General Methods Department Manager
Telephone : +33 1 57 61 25 72
Email : jacques.leroux@sagemcom.com

Date : March 06, 2018

