

Seeing Machines Ltd.
80 Mildura St. Fyshwick
ACT 2609 AUSTRALIA

MADE IN CHINA



FCC ID: W5Y-1002244

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

MFR: ADLINK TECHNOLOGY INC.

MODEL (SYSTEM): G2-SY-CON2

TYPE: G2-SY-CON2-1002244

BT ADDRESS: BB:BB:BB:BB:BB:BB

VERSION-DATE CODE: VV-WWYY

IMEI: AA-BBBBBB-CCCCC-D

INPUT: 10-30VDC

SN: P1234567-S12345678

Seeing Machines Ltd.
 80 Midvale St, Pyrmont
 NSW 2009 Australia

MADE IN CHINA

FCC CE

FCC ID: W5Y-1002244

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

MFR: ADLINK TECHNOLOGY INC.
 MODEL (SYSTEM): G2-SP-CON2
 TYPE: G2-SP-CON2-1002244
 BT ADDRESS: **SP-00-00-00-00-00**
 VERSION-DATE CODE: **V1-15WVY**
 IMEI: **359407000000000**
 INPUT: 10-30VDC
 SN: **112345678**

 seeingmachines

GUARDIAN SPLIT CONTROLLER

G2-SP-CON2-1001229

