

Request for Class II Permissive Change

FCC ID: W9HLCDC0023

Date: Apr 18, 2014

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Add a new tuner
2. Some circuits around the tuner are changed

Please refer to below form for details information:

Item	Key Components Deviation		Remark
Tuner	DVTX-9D/W41F2\ROH	SDVT-10A/WF2\ROH	Change the tuner

Remark:

The date of original grant is Jul 31, 2013.

Thank you.

Sincerely,



Lulu Tang / Supervisor

Hisense Electric Co., Ltd.

Tel: (+86-532)80874377

Fax: (+86-532)80874665

Email: tanglulu@hisense.com