



SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA, EU

06-MXM MkX

Tx: 5739.00 - 5741.00 MHz Rx: 5834.00 - 5836.00 MHz FCC ID: W9Z-58F2DMXMRX ICID: 8855A-58F2DMXMRX

N: G06S2118L

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA, EU

06-MXM MkX

Tx: 5834.00 - 5836.00 MHz Rx: 5739.00 - 5741.00 MHz FCCID: W9Z-58F2DMXMRX

ICID: 8855A-58F2DMXMRX

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Rogers Labs, Inc. SAF Tehnika AS S/N's: 331690100444/331700100445

Model: CFL Sprint MXM MkX Repeater 4405 W. 259th Terr FCC ID: W9Z-58F2DMXMRX

Louisburg, KS 66053 Test: 200910 IC: 8855A-58F2DMXMRX Phone/Fax: (913) 837-3214 Test to: 47CFR, 15.407, RSS-247 Date: November 25, 2020

Revision 1 File: 58F2DMXMRX LabelSmp Page 1 of 4

SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA. EU

06-MXM MkX

Tx: 5739.00 - 5741.00 MHz Rx: 5834.00 - 5836.00 MHz

FCCID: W9Z-58F2DMXMRX ICID:8855A-58F2DMXMRX



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA. EU

06-MXM MkX

Tx: 5834.00 - 5836.00 MHz Rx: 5739.00 - 5741.00 MHz

FCCID: W9Z-58F2DMXMRX ICID: 8855A-58F2DMXMRX



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Rogers Labs, Inc. SAF Tehnika AS S/N's: 331690100444/331700100445

4405 W. 259th Terr Model: CFL Sprint MXM MkX Repeater FCC ID: W9Z-58F2DMXMRX

Louisburg, KS 66053 Test: 200910 IC: 8855A-58F2DMXMRX Phone/Fax: (913) 837-3214 Test to: 47CFR, 15.407, RSS-247 Date: November 25, 2020

Revision 1 File: 58F2DMXMRX LabelSmp Page 2 of 4

SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA. EU

06-MXM MkX

Tx: 5739.00 - 5741.00 MHz Rx: 5834.00 - 5836.00 MHz

FCCID: W9Z-58F2DMXMRX ICID:8855A-58F2DMXMRX



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA. EU

06-MXM MkX

Tx: 5834.00 - 5836.00 MHz Rx: 5739.00 - 5741.00 MHz

FCCID: W9Z-58F2DMXMRX ICID:8855A-58F2DMXMRX

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Rogers Labs, Inc. SAF Tehnika AS S/N's: 331690100444/331700100445

4405 W. 259th Terr Model: CFL Sprint MXM MkX Repeater FCC ID: W9Z-58F2DMXMRX Louisburg, KS 66053 Test: 200910 IC: 8855A-58F2DMXMRX

Phone/Fax: (913) 837-3214 Test to: 47CFR, 15.407, RSS-247 Date: November 25, 2020

Revision 1 File: 58F2DMXMRX LabelSmp Page 3 of 4

SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA. EU

06-MXM MkX

Tx: 5739.00 - 5741.00 MHz Rx: 5834.00 - 5836.00 MHz

FCCID: W9Z-58F2DMXMRX ICID:8855A-58F2DMXMRX



This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



SAF Tehnika AS 24a Ganibu dambis Riga, LV-1005 Made in LATVIA. EU

06-MXM MkX

Tx: 5834.00 - 5836.00 MHz Rx: 5739.00 - 5741.00 MHz

FCCID: W9Z-58F2DMXMRX ICID:8855A-58F2DMXMRX

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Rogers Labs, Inc. SAF Tehnika AS S/N's: 331690100444/331700100445

4405 W. 259th Terr Model: CFL Sprint MXM MkX Repeater FCC ID: W9Z-58F2DMXMRX Test: 200910 IC: 8855A-58F2DMXMRX

Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Test to: 47CFR, 15.407, RSS-247 Date: November 25, 2020

Revision 1 File: 58F2DMXMRX LabelSmp Page 4 of 4