

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission **Below 1 GHz**



Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission
Above 1 GHz




Photo 1




Photo 2

Worst Case Position


Below 1 GHz : (Horizontal: X-axis/ Vertical:Y-axis)

Above 1 GHz : (Horizontal: Z-axis/ Vertical:Y-axis)


X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124