

AUDIX Technology Corp.


No. 53-11, Dingfu, Linkou, Dist.,

New Taipei City 244, Taiwan

Tel: +886 2 26099301


Fax: +886 2 26099303

Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT20	UNII Band	I
Cable Loss	1.6dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT20	UNII Band	I
Cable Loss	1.6dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT20	UNII Band	I
Cable Loss	1.6dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT20	UNII Band	II-2A
Cable Loss	1.6B	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	4.77		






Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT20	UNII Band	II-2A
Cable Loss	1.6B	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


20GHz – 25GHz




25GHz – 30GHz




30GHz – 35GHz



35GHz – 40GHz




Test Date	2016/06/15	Temp./Hum.	25°C/55%
Mode	802.11ac-VHT20	UNII Band	II-2A
Cable Loss	1.6dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2016/05/24	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2016/05/24	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5600MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2016/05/24	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Test Date	2016/05/25	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5720MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		



AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2016/05/24 ~ 25	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3






AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/05/24	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		




AUDIX Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


20GHz – 25GHz




25GHz – 30GHz




30GHz – 35GHz




35GHz – 40GHz




Test Date	2016/05/24 ~ 25	Temp./Hum.	26°C/54%
Mode	802.11ac-VHT20	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60HZ
			3




15GHz – 20GHz




20GHz – 25GHz



25GHz – 30GHz



30GHz – 35GHz



35GHz – 40GHz

