

09 January 2009

American TCB  
6731 Whittier Avenue  
McLean VA 22101

RE: Destron Fearing Corporation  
Response to 31 December 2008 Comments

FCC ID: WMQ800962

In response to your comments on the above submittal from 31 December 2008.

1. ATCB Comments: Manual also needs FCC Compliance Statement:  
For receivers and Class B digital

This product has been tested and complies with the specifications for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used according to the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which is found by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

Reorient or relocate the receiving antenna

Increase the separation between the equipment or devices

Connect the equipment to an outlet other than the receiver's

Consult a dealer or an experienced radio/TV technician for assistance

**RESPONSE: Revised manual has been uploaded.**

2. ATCB Comments: Users Manual must have Pt. 15.21 statement.  
Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

**RESPONSE: Revised manual has been uploaded.**

3. ATCB Comments: The IC label must also have the model number on it as well as manufacturer.

**RESPONSE: A revised label exhibit has been uploaded.**

4. ATCB Comments: Please complete the Annex B form for Industry Canada and upload.

**RESPONSE: Done.**

Please let us know if anything further is required.

*Susan L Rupp*

Susan L Rupp, Technical Writer  
TÜV America Inc  
Tel: 651 638 4585 / Fax: 651 638 0298  
srupp@tuvam.com