

Paper label BE1283 NAM

Material: Indelible tamper-proof Label

Bellman Visit 433 Smoke alarm BE1283
9V Photoelectric smoke alarm. For installation see owners manual.

CAUTION No user servicable parts inside. Use only specified batteries. The use of different batteries may have a detrimental effect on operation or may cause the battery to explode resulting in injury or fire. Constant exposure to high or low temperatures or high humidity can reduce battery life. Test the alarm for correct operation using the test facility, whenever the battery is replaced. Replace the battery with Duracell #MX1604, Energizer #522, Ultralife U9VL-J-P or FDK CP-V9J. Aural alarm signal ISO7731 at 85 dB/3m. Test unit weekly. Clean with vacuum. Return to supplier for service. Replace this alarm after 10 years.

For product or warranty enquires, contact
Bellman & Symfon AB, S. Långebergsgatan
30, SE-421 32 Västra Frölunda, Sweden.
info@bellman.com bellman.com

MFG date:
Replace by:
Batch no.
BE1283_013LRL001 MADE IN CHINA

This device complies with Part 15 of the FCC Rules and Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions:
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received, including interference that may cause undesired operation.
M/N: BE1283; FCC ID: WMSBETXSA; IC: 6693A-BETXSA