


INTERTEK TESTING SERVICES

Report No.: HK08081557



Ref -30 dBm *Att 0 dB *RBW 100 kHz Marker 1 [T1]
*VBW 100 kHz -82.59 dBm
*SWT 100 ms 314.794000000 MHz



Date: 10.SEP.2008 14:17:05