






# INTERTEK TESTING SERVICES

Report No.: HK08081557



RBW 300 kHz Delta 1 [T1 ]  
VBW 1 MHz 4.43 dB  
Ref -30 dBm \*Att 0 dB SWT 10 ms 2.919000 ms



Center 315.06794 MHz 1 ms/


Date: 10.SEP.2008 14:51:17

# INTERTEK TESTING SERVICES

Report No.: HK08081557



RBW 300 kHz Marker 1 [T1 ]  
VBW 1 MHz -63.55 dBm  
Ref -30 dBm \*Att 0 dB SWT 10 s 100.000000 ms




Date: 10.SEP.2008 14:27:24

# INTERTEK TESTING SERVICES

Report No.: HK08081557



RBW 300 kHz Marker 1 [T1 ]  
VBW 1 MHz -62.06 dBm  
Ref -30 dBm \*Att 0 dB SWT 500 ms 103.000000 ms



Date: 10.SEP.2008 14:32:35