

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC

INTERNAL PHOTOGRAPHS



Figure 1. Enclosure Open

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC



Figure 2. NFC Board Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC




Figure 3. Top of NFC Board/Bare Board Option

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC



Figure 4. Bottom of NFC Board/Bare Board Option

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC




Figure 5. Carrier PCB with Core PCB Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC




Figure 6. Core PCB Top Side

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
WP5TWN4F1
7948A-TWN4F1
15-0269
December 23, 2015
ELATEC
TWN4 Mifare NFC




Figure 7. Core PCB Bottom Side