

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense

---

## EXTERNAL PHOTOGRAPHS




Photo 1 – Top of EUT

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense



**Photo 2 – Back of EUT**

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense



Photo 3 – Back of EUT, Close Up

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense



Photo 4 – Left Side of EUT

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense

---



**Photo 5 – Top of EUT**

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense



**Photo 6 – Top of EUT, Close Up**



US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense



**Photo 7 – Right Side of EUT**

US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense

---



**Photo 8 – Bottom of EUT**



US Tech  
Test Report:  
Date:  
Model(s):  
FCC ID  
IC:  
Customer:

FCC Part 15.247/ RSS 210  
14-0123  
September 8, 2014  
PSASII-01  
WPEPSASII-01  
8031A-PSASII01  
Paksense

---



**Photo 9 – Bottom of EUT, Close Up**