









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (160) / (250) Pages



**ANT1\_802.11ac\_VHT20\_UNII 2C**






**ANT1\_802.11ac\_VHT20\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (161) / (250) Pages



**ANT2\_802.11ac\_VHT20\_UNII 1**






**ANT2\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501




Report No.:  
CTK-2021-00840  
Page (162) / (250) Pages






### ANT2\_802.11ac\_VHT20\_UNII 2C



### ANT2\_802.11ac\_VHT20\_UNII 3



**ANT3\_802.11ac\_VHT20\_UNII 1**






**ANT3\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (164) / (250) Pages



**ANT3\_802.11ac\_VHT20\_UNI1 2C**






**ANT3\_802.11ac\_VHT20\_UNI1 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (165) / (250) Pages



**ANT4\_802.11ac\_VHT20\_UNII 1**






**ANT4\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-00840  
Page (166) / (250) Pages



ANT4\_802.11ac\_VHT20\_UNI1 2C





ANT4\_802.11ac\_VHT20\_UNI1 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (167) / (250) Pages



**ANT1\_802.11n\_HT40\_UNII 1**



**ANT1\_802.11n\_HT40\_UNII 2A**





**ANT1\_802.11n\_HT40\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (168) / (250) Pages





ANT1\_802.11n\_HT40\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (169) / (250) Pages



**ANT2\_802.11n\_HT40\_UNII 1**



**ANT2\_802.11n\_HT40\_UNII 2A**





**ANT2\_802.11n\_HT40\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (170) / (250) Pages





ANT2\_802.11n\_HT40\_UNII 3





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501




Report No.:  
CTK-2021-00840  
Page (171) / (250) Pages



**ANT3\_802.11n\_HT40\_UNII 1**



**ANT3\_802.11n\_HT40\_UNII 2A**





**ANT3\_802.11n\_HT40\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (172) / (250) Pages





ANT3\_802.11n\_HT40\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (173) / (250) Pages



**ANT4\_802.11n\_HT40\_UNII 1**



**ANT4\_802.11n\_HT40\_UNII 2A**





**ANT4\_802.11n\_HT40\_UNII 2C**





**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501



Report No.:  
CTK-2021-00840  
Page (174) / (250) Pages





ANT4\_802.11n\_HT40\_UNII 3



**ANT1\_802.11ac\_VHT40\_UNII 1**



**ANT1\_802.11ac\_VHT40\_UNII 2A**





**ANT1\_802.11ac\_VHT40\_UNII 2C**







**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501



Report No.:  
CTK-2021-00840  
Page (176) / (250) Pages






ANT1\_802.11ac\_VHT40\_UNII 3



**ANT2\_802.11ac\_VHT40\_UNII 1**



**ANT2\_802.11ac\_VHT40\_UNII 2A**





**ANT2\_802.11ac\_VHT40\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2021-00840  
 Page (178) / (250) Pages






ANT2\_802.11ac\_VHT40\_UNII 3



**ANT3\_802.11ac\_VHT40\_UNII 1**



**ANT3\_802.11ac\_VHT40\_UNII 2A**





**ANT3\_802.11ac\_VHT40\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (180) / (250) Pages





ANT3\_802.11ac\_VHT40\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (181) / (250) Pages



**ANT4\_802.11ac\_VHT40\_UNII 1**



**ANT4\_802.11ac\_VHT40\_UNII 2A**





**ANT4\_802.11ac\_VHT40\_UNII 2C**




**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501


Report No.:  
CTK-2021-00840  
Page (182) / (250) Pages





ANT4\_802.11ac\_VHT40\_UNII 3




**ANT1\_802.11ac\_VHT80\_UNII 1**



**ANT1\_802.11ac\_VHT80\_UNII 2A**




**ANT1\_802.11ac\_VHT80\_UNII 2C**




**ANT1\_802.11ac\_VHT80\_UNII 3**








**ANT2\_802.11ac\_VHT80\_UNII 1**




**ANT2\_802.11ac\_VHT80\_UNII 2A**




**ANT2\_802.11ac\_VHT80\_UNII 2C**





**ANT2\_802.11ac\_VHT80\_UNII 3**




**ANT3\_802.11ac\_VHT80\_UNII 1**




**ANT3\_802.11ac\_VHT80\_UNII 2A**




**ANT3\_802.11ac\_VHT80\_UNII 2C**





**ANT3\_802.11ac\_VHT80\_UNII 3**




**ANT4\_802.11ac\_VHT80\_UNII 1**



**ANT4\_802.11ac\_VHT80\_UNII 2A**



**ANT4\_802.11ac\_VHT80\_UNII 2C**



**ANT4\_802.11ac\_VHT80\_UNII 3**