









CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (99) / (250) Pages



ANT3_802.11n_HT20_UNII 1






ANT3_802.11n_HT20_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (100) / (250) Pages



ANT3_802.11n_HT20_UNII 2C






ANT3_802.11n_HT20_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (101) / (250) Pages



ANT4_802.11n_HT20_UNII 1






ANT4_802.11n_HT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (102) / (250) Pages



ANT4_802.11n_HT20_UNII 2C






ANT4_802.11n_HT20_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (103) / (250) Pages



ANT1_802.11ac_VHT20_UNII 1






ANT1_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (104) / (250) Pages



ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (105) / (250) Pages



ANT2_802.11ac_VHT20_UNII 1






ANT2_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (106) / (250) Pages



ANT2_802.11ac_VHT20_UNII 2C






ANT2_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (107) / (250) Pages



ANT3_802.11ac_VHT20_UNII 1






ANT3_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (108) / (250) Pages



ANT3_802.11ac_VHT20_UNII 2C






ANT3_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (109) / (250) Pages



ANT4_802.11ac_VHT20_UNII 1






ANT4_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (110) / (250) Pages



ANT4_802.11ac_VHT20_UNII 2C




ANT4_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-00840
 Page (111) / (250) Pages



ANT1_802.11n_HT40_UNI I 1



ANT1_802.11n_HT40_UNI I 2A





ANT1_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (112) / (250) Pages





ANT1_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-00840
 Page (113) / (250) Pages



ANT2_802.11n_HT40_UNI I 1



ANT2_802.11n_HT40_UNI I 2A





ANT2_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (114) / (250) Pages





ANT2_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-00840
 Page (115) / (250) Pages



ANT3_802.11n_HT40_UNI I 1



ANT3_802.11n_HT40_UNI I 2A





ANT3_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (116) / (250) Pages





ANT3_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-00840
 Page (117) / (250) Pages



ANT4_802.11n_HT40_UNI I 1



ANT4_802.11n_HT40_UNI I 2A





ANT4_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (118) / (250) Pages





ANT4_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-00840
 Page (119) / (250) Pages



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00840
 Page (120) / (250) Pages





ANT1_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-00840
 Page (121) / (250) Pages



ANT2_802.11ac_VHT40_UNI I



ANT2_802.11ac_VHT40_UNI I 2A





ANT2_802.11ac_VHT40_UNI I 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (122) / (250) Pages





ANT2_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-00840
Page (123) / (250) Pages



ANT3_802.11ac_VHT40_UNII 1



ANT3_802.11ac_VHT40_UNII 2A





ANT3_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-00840
Page (124) / (250) Pages





ANT3_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-00840
Page (125) / (250) Pages



ANT4_802.11ac_VHT40_UNI I



ANT4_802.11ac_VHT40_UNI I 2A



ANT4_802.11ac_VHT40_UNI I 2C