








MC-i3 GNSS Receiver Labeling Information

FCC ID: WR4-MC-I3
IC: 6050B-MCI3

MODEL 1000082-08

<p>Model: 1000082-08</p>  <p>S/N: 1194-XXXXX</p>  <p>This unit is configured with a Topcon FH915+ Modem with H24.</p>	<p>This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.</p> <p>FCC ID: WR4-MC-I3 IC: 6050B-MCI3 Contains FCC ID: R17T56KL1 Contains IC: 5131A-KL1</p>
 N 13813 Made in USA 	

MODEL 1000082-09

<p>Model: 1000082-09</p>  <p>S/N: 1186-XXXXX</p>  <p>This unit is configured with a Topcon FH915+ Modem with H24.</p>	<p>This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.</p> <p>FCC ID: WR4-MC-I3 IC: 6050B-MCI3 Contains FCC ID: R17T56KL1 Contains IC: 5131A-KL1</p>
 N 13813 Made in USA 	

TOP ENCLOSURE



BOTTOM ENCLOSURE

