

**Doro AB**



Date: Jun. 21, 2021

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: WS5DFC0270  
Original Grant Date: 8/8/2019  
Applicant: Doro AB

Ref: FCC Class II Permissive change for FCC ID: WS5DFC0270  
Original Grant Date: 10/23/2020  
Applicant: Doro AB

Doro AB



## Product Change Description

As the applicant of the below model, [Doro AB] declares that the product,

[DFC-0270]

[Doro AB]

HW: V01C(HW code: 5011/5061/5071/5081/5091/5101)

SW: DFC0270\_VF292\_N\_S01A\_V18\_M210325\_CE

is the variant of the initial certified product,

[DFC-0270]

[Doro AB]

HW: V01C(HW code: 4011/4021/5011/5021/5031/5041)

SW: DFC0270\_VF292\_N\_S01A\_V16\_M200729\_GCF

### SOFTWARE MODIFICATIONS:

Protocol Stack changes: NO

MMS/SUPL changes: NO

STK/USAT changes: NO

Browsing changes: NO

Other changes detailed: YES, only modify IMEI SV, no other changes

### HARDWARE MODIFICATION:

Band changes: NO

Power Amplifier changes: YES, only Audio PA changes

Antenna changes: NO

PCB Layout changes: No

Components on PCB changes: YES, CPU changes

CPU changes: YES, add MT8765 V/WBZA, same electrical characteristics in SoC, only printing is different

LCD changes: YES, add new Main LCD

Memory changes: NO

Speaker changes: NO

Camera changes: YES, add a new Rear camera

Vibrator changes: NO

Bluetooth changes: NO



Doro AB

FM changes: NO

Other changes: NO

**MECHANICAL MODIFICATIONS:**

Use new metal front/back cover or keypad: NO

Mechanical shell changes: NO

Other changes detailed: NO

**ACCESSORY MODIFICATIONS:**

Battery changes: NO

AC Adaptor changes: NO

Earphone changes: NO

**Signature:**

A handwritten signature in blue ink, appearing to read "Fredrik Bengtsson".

**Print name:** Fredrik Bengtsson/R&D DIRECTOR PHONES

**Date:** June 17, 2021

**Company:** Doro AB

**Address:** Jörgen Kocksgatan 1B, SE 211 20 MALMÖ, SWEDEN