

# INTERTEK TESTING SERVICES

Report No.: HK09020879-2  
B2A




\*RBW 100 kHz Delta 1 [T1 ]  
VBW 300 kHz 0.36 dB  
\*SWT 500 ms 1.620000000 MHz

Ref 10 dBm

Att 40 dB

1 PK  
VIEW



Center 2.40496 GHz

500 kHz/

Span 5 MHz


Date: 23.APR.2009 10:35:08

# INTERTEK TESTING SERVICES

Report No.: HK09020879-2  
B2B



Ref 10 dBm Att 40 dB \*RBW 100 kHz Delta 1 [T1 ]  
VBW 300 kHz 0.55 dB  
\*SWT 500 ms 1.630000000 MHz



Date: 23.APR.2009 10:47:12

# INTERTEK TESTING SERVICES

Report No.: HK09020879-2  
B2C




\*RBW 100 kHz Delta 1 [T1 ]  
VBW 300 kHz 0.46 dB  
\*SWT 500 ms 1.650000000 MHz

Ref 10 dBm

Att 40 dB

1 PK  
VIEW



Center 2.48 GHz

500 kHz/

Span 5 MHz

Date: 23.APR.2009 10:44:59