

# INTERTEK TESTING SERVICES

Report No.: HK09020879-2  
B3A




\*RBW 3 kHz      Marker 1 [T1 ]  
VBW 10 kHz      -11.31 dBm  
\*SWT 500 s      2.405054000 GHz

Ref 10 dBm

Att 40 dB

1 PK  
VIEW



A

Center 2.405 GHz

150 kHz/

Span 1.5 MHz

Date: 23.APR.2009 15:33:47

# INTERTEK TESTING SERVICES

Report No.: HK09020879-2  
B3B




\*RBW 3 kHz      Marker 1 [T1 ]  
VBW 10 kHz      -11.63 dBm  
\*SWT 500 s      2.440417000 GHz

Ref 10 dBm

Att 40 dB

1 PK  
VIEW



Center 2.44 GHz

150 kHz/

Span 1.5 MHz

Date: 23.APR.2009 15:56:07

# INTERTEK TESTING SERVICES

Report No.: HK09020879-2  
B3C




\*RBW 3 kHz      Marker 1 [T1 ]  
VBW 10 kHz      -12.92 dBm  
\*SWT 500 s      2.480417000 GHz

Ref 10 dBm

Att 40 dB

1 PK  
VIEW



Center 2.48 GHz

150 kHz/

Span 1.5 MHz

Date: 23.APR.2009 16:06:11