



July 26th, 2010

SUBJECT: TIMCO-TCB/Request for additional info - TELTRONIC, S.A.U - FCC ID:
WTP-400RFU

REFERENCE: JOB 550AUT10

To who it may concern,

I'm requesting that the test report be superseded because of a clerical error that allowed the wrong modulation limiting plots to be included.

Regards,

Mario de Aranzeta
Test Engineer/ Lab Supervisor
Timco Engineering Inc.