



Date: 30 AUG 2016

Ref: Justification for placing the FCC ID/ID in the user manual for model CP1000

FCC ID: WTO-CP1000

IC: 8039A-CP1000

We, Cochlear Limited, located on 1 University Avenue, Macquarie University, NSW, 2109 Australia, hereby state that there are two main reasons why the device stated above does not have FCC/IC marks:

- 1) The top and bottom housing can be removed and they are not permanent locations to place the regulatory labels.
- 2) The only permanent location is too small to have visible text (smaller than 4-6 points)

Therefore, FCC ID and the IC information are included in the user manual which will be supplied together with the device.

Sincerely,

BY: LISA EMERSON

diesa Emercian

Title: SVP Quality

Company: Cochlear Limited

E-mail: lemerson @ cochieor. com.