

TRP Inc.

June 11, 2009

Federal Communications Commission
Laboratory Division
7435 Oakland Mills Rd
Columbia, MD 21045

Gentlemen:

Submitted herewith is a request for certification of a Medical Communications system transmitter, FCC ID: WTOCP81000, that is part of a Medical Communications System. This device is worn behind the ear of the patient and operates on a channel selected by the external remote assistance transmitter. For further information see the operational description.

Pursuant to Sections 2.925(f) and 15.19(a)(5) this device is too small to carry the FCC ID and compliance statement on the unit and it is therefore requested that the FCC accept an alternate identification method. The FCC ID and compliance statements have been included in the patient user manual in lieu of placing it on the unit. There is insufficient room on the device for a legible FCC ID number to be placed on it. Further, the sound processors' housing is worn in direct contact with the skin which would make it difficult to keep a label on the device and in some cases would cause an allergic reaction with the skin of the patient.

If you have any questions, please call Phillip Inglis at 410 531 3439 or contact via email at jinglis@erols.com. It is also requested that you forward copies of any correspondence and authorization documents to the email address specified above.

Sincerely,



Phillip Inglis
Consultant to Cochlear Corp.