


Report No. : FA381602


Appendix D. Test Setup Photos



Right Cheek with Cover Back



Right Cheek with Cover Front



Left Cheek with Cover Back



Left Cheek with Cover Front



Right Tilted with Cover Back




Left Tilted with Cover Back

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA792X Page Number : D1 of D2 Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01






Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA792X Page Number : D2 of D2
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01