



8. APPENDIX I PHOTOGRAPHS OF TEST SETUP

RADIATED MEASUREMENT SETUP

Adapter1: FRA05-S05-1





Adapter2: TEKA006-0501000UK





Normal Operation





RADIATED RF EMISSION MEASUREMENT SETUP(FOR TX)







POWERLINE CONDUCTED EMISSIONS SETUP

Adapter1: FRA05-S05-1





Adapter2: TEKA006-0501000UK

