



## 8. APPENDIX I PHOTOGRAPHS OF TEST SETUP

### RADIATED MEASUREMENT SETUP

Adapter1: FRA05-S05-1





**Adapter2: TEKA006-0501000UK**





**Normal Operation**






### RADIATED RF EMISSION MEASUREMENT SETUP(FOR TX)






## POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





## **POWERLINE CONDUCTED EMISSIONS SETUP**

**Adapter1: FRA05-S05-1**





**Adapter2: TEKA006-0501000UK**

