



UL Korea, Ltd

[www.ulk.co.kr](http://www.ulk.co.kr)

Project: 10CA05635  
File: TC8389  
Report 10CA05635-FCC  
Date: March 10, 2010  
Model: FireCR (Basic) and VetCR

## Internal Photos For Computed Radiography Scanner

**3D Imaging & Simulations Corp.  
49-3, Moonpyung-Dong, Daedeok-Gu, Daejeon, Korea**

**Copyright © 2005 Underwriters Laboratories Inc.**

33rdFl. Gangnam finance Center, 737 Yeoksam-Dong, Kangnam-Gu, Seoul, 135-984, Korea  
Underwriters Laboratories Inc. authorizes the above-named company to reproduce this Report provided it is  
reproduced in its entirety.

---

UL Korea, Ltd  
33<sup>rd</sup> FL, Gangnam Finance Center, 737  
Yeoksam-dong, Gangnam-gu, Seoul  
135-984 Korea  
Tel: +82.2.2009.9000, Fax: +82.2.2009.9405

A not-for-profit organization dedicated  
to public safety and committed to  
quality service for over 100 years

Project Number:  
Model Number:


10CA05635  
FireCR

File Number


TC8389

Test Report No: 10CA05635-FCC  
Date of Issue: March 10, 2010

Inside 1




Main board front




Project Number: 10CA05635 File Number: TC8389 Test Report No: 10CA05635-FCC  
Model Number: FireCR Date of Issue: March 10, 2010

Main board rear




Main board front




Project Number: 10CA05635 File Number: TC8389 Test Report No: 10CA05635-FCC  
Model Number: FireCR Date of Issue: March 10, 2010

Sub board front



Sub board rear



Project Number:  
Model Number:


10CA05635  
FireCR

File Number

TC8389

Test Report No: 10CA05635-FCC  
Date of Issue: March 10, 2010

Power switch board front



Power switch board rear

