



SureFlap Ltd
7 The Irwin Centre
Scotland Road
Dry Drayton
Cambs
CB23 8AR

Telecommunication Certification Body
UL VS Ltd
Unit 3, Horizon
Wade Road
Kingsland Business Park
Basingstoke
Hampshire
RG24 8AH
United Kingdom

Tel: 01954 211664
Email: enquiries@sureflap.co.uk
Website: www.sureflap.com

25 October 2016

Subject: Hardware and Software Change
FCC Number: XO9-HR000N

To whom it may concern,

We, SureFlap Ltd, hereby attest that the model: HRP, has undergone the following hardware changes from v04 to v06:

- Layout of Bluetooth radio bias current circuit shortened and series inductor removed.
- Layout of Bluetooth radio impedance matching circuit changed.
- Two high-frequency inductors added to microcontroller power supply.
- Layout of microcontroller power supply decoupling capacitors changed.

We further attest that the same model has undergone the following software changes from version 54 to 93:

- Maximum Bluetooth radio power output set at -3 dBm.
- USB & Bluetooth application-level interface updates.
- User Interface updates.

These changes have no effect on the operation of the RFID circuit.

Yours faithfully,

Chris Cowdery, Head of Embedded Systems