

FCC details

FRN: 0019054196
FCC ID: X09-MPF001-002
Model ID: MPF001

ISED details

IC Company No.: 8906A
Certification No.: 8906A-MPF01002
Model No.: MPF001



6-7 The Irwin Centre
Scotland Road
Dry Drayton
Cambridge
CB23 8AR
United Kingdom

Tel: +44 (0)1954 211 664

surepetcare.com

Internal Product Images

General Product image with base removed



Front view

FCC details

FRN: 0019054196
FCC ID: X09-MPF001-002
Model ID: MPF001

ISED details

IC Company No.: 8906A
Certification No.: 8906A-MPF01002
Model No.: MPF001



6-7 The Irwin Centre
Scotland Road
Dry Drayton
Cambridge
CB23 8AR
United Kingdom


Tel: +44 (0)1954 211 664

surepetcare.com

Lefthand side view



Righthand side view



FCC details

FRN: 0019054196
FCC ID: X09-MPF001-002
Model ID: MPF001

ISED details

IC Company No.: 8906A
Certification No.: 8906A-MPF01002
Model No.: MPF001




6-7 The Irwin Centre
Scotland Road
Dry Drayton
Cambridge
CB23 8AR
United Kingdom

Tel: +44 (0)1954 211 664

surepetcare.com

Motor assembly top side



Motor assembly reverse side



Switch PCB component side



FCC details

FRN: 0019054196
FCC ID: X09-MPF001-002
Model ID: MPF001

ISED details

IC Company No.: 8906A
Certification No.: 8906A-MPF01002
Model No.: MPF001



6-7 The Irwin Centre
Scotland Road
Dry Drayton
Cambridge
CB23 8AR
United Kingdom


Tel: +44 (0)1954 211 664

surepetcare.com


Switch PCB reverse side



Main PCB reverse side



Main PCB component side



FCC details

FRN: 0019054196
FCC ID: XO9-MPF001-002
Model ID: MPF001

ISED details

IC Company No.: 8906A
Certification No.: 8906A-MPF01002
Model No.: MPF001



6-7 The Irwin Centre
Scotland Road
Dry Drayton
Cambridge
CB23 8AR
United Kingdom

Tel: +44 (0)1954 211 664

surepetcare.com

Detector PCB transmitter and receiver

