



Fender Musical Instruments Corporation
17600 N. Perimeter Drive Suite 100, Scottsdale, Arizona, 85255, United States

Request for Class II Permissive Change

FCC ID: XQW-FBTPR5380

Date: 2018-1-23

To: Federal Communication Commission

Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

Please be notified that we, the undersigned, (Fender Musical Instruments) declare that the reasons for this Class II permissive change are as below:

There are identical main body/function as following:

Printed Circuit Board (PCB)

Hardware


Software

Enclosure


Internal structure

There is difference as following:

- 1) Cable length is different PureSonic Premium Wireless's cable is 65mm longer than that of Puresonic Wireless with metal wire and vinyl tube.
- 2) Earpiece shape and internal structure is different.



PS Premium Wireless



PS Wireless

- 3) Driver diameter is different. Driver of PureSonic Premium Wireless is 9.25mm in diameter which driver of Puresonic Wireless is 6mm.

Sincerely,

By:

(Signature¹)

Larry Clauss

(Print name)

Title: Principal Engineer Compliance

On behalf of: Fender Musical Instruments
(Company Name)

Telephone: +1 (480) 845-5203