


Test Date	2018/03/26	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5700MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26~29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	1.74dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26~29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	1.74dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26~29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	1.74dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26~28	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	I
		Frequency	TX 5190MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		6.02	





Test Date	2018/03/26~28	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	I
		Frequency	TX 5230MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2018/03/26	Temp./Hum.	25°C /54%
Mode	802.11ac-VHT40	UNII Band	II-2A
		Frequency	TX 5270MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	





Test Date	2018/03/26	Temp./Hum.	25°C /54%
Mode	802.11ac-VHT40	UNII Band	II-2A
		Frequency	TX 5310MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)		6.02	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	II-2C
		Frequency	TX 5510MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	II-2C
		Frequency	TX 5550MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	II-2C
		Frequency	TX 5670MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2018/03/26~28	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	III
		Frequency	TX 5755MHz
Cable Loss	1.74dB	Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		6.02	





Test Date	2018/03/26~28	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT40	UNII Band	III
Cable Loss	1.74dB	Frequency	TX 5795MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02





Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2018/03/26	Temp./Hum.	25°C/54%
Mode	802.11ac-VHT80	UNII Band	I
Cable Loss	1.74dB	Frequency	TX 5210MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	AC 120V, 60Hz (via AC/DC Adapter)
			6.02

