


|   |   |                                   |              |
|---|---|-----------------------------------|--------------|
|  | Report No: <b>R3110</b><br>Issue No: <b>1</b> | FCC ID: XX6-STP8080 / XX6-STP8280 |              |
|   | Test No: <b>T4353</b>                         | <b>Test Photos</b>                | Page: 1 of 6 |



**dB Technology**

|----- ( Cambridge Ltd. ) -----|

EMC  
Testing

EMC  
Consultancy

EMC  
Training

23, Headington Drive,  
Cambridge.  
CB1 9HE  
Tel : 01954 251974 (test site)  
or : 01223 241140 (accounts)  
Fax : 01954 251907  
web : [www.dbtechnology.co.uk](http://www.dbtechnology.co.uk)  
email: [mail@dbtechnology.co.uk](mailto:mail@dbtechnology.co.uk)

## Test Photos

Performed at:  
**TWENTY PENCE TEST SITE**

Twenty Pence Road,  
Cottenham,  
Cambridge  
U.K.  
CB24 8PS

on

Sepura PLC

STP8080/STP8280

dated


22nd June 2012

### Document History

| Issue | Date     | Affected page(s) | Description of modifications | Revised by | Approved by |
|-------|----------|------------------|------------------------------|------------|-------------|
| 1     | 04/07/12 |                  | Initial release              |            |             |
|       |          |                  |                              |            |             |
|       |          |                  |                              |            |             |
|       |          |                  |                              |            |             |
|       |          |                  |                              |            |             |


Based on report template:  
v090319


*This report shall not be reproduced except in full, without the written approval of:  
dB Technology (Cambridge) Ltd.*

|   |   |                                   |              |
|---|---|-----------------------------------|--------------|
|  | Report No: <b>R3110</b><br>Issue No: <b>1</b> | FCC ID: XX6-STP8080 / XX6-STP8280 |              |
|   | Test No: <b>T4353</b>                         | <b>Test Photos</b>                | Page: 2 of 6 |




**Photograph 1 STP8080: Connected to Agilent Analyser**

|   |                         |                                   |                     |
|---|-------------------------|-----------------------------------|---------------------|
|  | Report No: <b>R3110</b> | FCC ID: XX6-STP8080 / XX6-STP8280 |                     |
|   | Issue No: <b>1</b>      |                                   |                     |
| Test No: <b>T4353</b>   | <b>Test Photos</b>      |                                   | Page: <b>3 of 6</b> |





**Photograph 2 Standalone: Radiated Emissions - Front**




**Photograph 3 Standalone: Radiated Emissions - Back**




|   |                         |                                   |              |
|---|-------------------------|-----------------------------------|--------------|
|  | Report No: <b>R3110</b> | FCC ID: XX6-STP8080 / XX6-STP8280 |              |
|   | Issue No: <b>1</b>      |                                   |              |
| Test No: <b>T4353</b>   | <b>Test Photos</b>      |                                   | Page: 4 of 6 |



**Photograph 4 With RSM: Radiated Emissions - Front**




**Photograph 5 With RSM: Radiated Emissions - Back**

|   |   |                                   |              |
|---|---|-----------------------------------|--------------|
|  | Report No: <b>R3110</b><br>Issue No: <b>1</b> | FCC ID: XX6-STP8080 / XX6-STP8280 |              |
|   | Test No: <b>T4353</b>                         | <b>Test Photos</b>                | Page: 5 of 6 |





**Photograph 6 Car Kit: Radiated Emissions - Front**




**Photograph 7 Car Kit: Radiated Emissions - Back**



|   |                         |                                   |              |
|---|-------------------------|-----------------------------------|--------------|
|  | Report No: <b>R3110</b> | FCC ID: XX6-STP8080 / XX6-STP8280 |              |
|   | Issue No: <b>1</b>      |                                   |              |
| Test No: <b>T4353</b>   | <b>Test Photos</b>      |                                   | Page: 6 of 6 |



**Photograph 8 STP8280: Radiated Emissions - Front**



**Photograph 9 STP8280: Radiated Emissions - Back**