	Report No: R3275 Issue No: 1	FCC ID: XX6STP9040/XX6STP9240	
	Test No: T5115		Test Photos



dB Technology
|----- (Cambridge Ltd.) -----|

EMC
Testing

EMC
Consultancy

EMC
Training

23, Headington Drive,
Cambridge.
CB1 9HE
Tel : 01954 251974 (test site)
or : 01223 241140 (accounts)
Fax : 01954 251907
web : www.dbtechnology.co.uk
email: mail@dbtechnology.co.uk

ELECTROMAGNETIC COMPATIBILITY TEST PHOTOS

Performed at:
TWENTY PENCE TEST SITE

**Twenty Pence Road,
Cottenham,
Cambridge
U.K.
CB24 8PS**

on

Sepura PLC

STP9040/STP9240

dated


15th December 2013


Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	15/12/13		Initial release		


Based on report template:
v090319

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*


	Report No: R3275 Issue No: 1	FCC ID: XX6STP9040/XX6STP9240	
	Test No: T5115		Test Photos



Photograph 1 Connected to Spectrum Analyser



Photograph 2 Connected to Tetra Test Set


	Report No: R3275	FCC ID: XX6STP9040/XX6STP9240	
	Issue No: 1		
	Test No: T5115	Test Photos	Page: 3 of 10




Photograph 3 Radiated Emissions - Standalone




Photograph 4 Radiated Emissions - Standalone


	Report No: R3275 Issue No: 1	FCC ID: XX6STP9040/XX6STP9240	
	Test No: T5115		Test Photos



Photograph 5 Radiated Emissions - Standalone



Photograph 6 Radiated Emissions - Standalone


	Report No: R3275	FCC ID: XX6STP9040/XX6STP9240	
	Issue No: 1		
Test No: T5115	Test Photos		Page: 5 of 10




Photograph 7 Radiated Emissions - STP9240




Photograph 8 Radiated Emissions - STP9240


	Report No: R3275 Issue No: 1	FCC ID: XX6STP9040/XX6STP9240	
	Test No: T5115		Page: 6 of 10



Photograph 9 Radiated Emissions - STP9240




Photograph 10 Radiated Emissions - STP9240


	Report No: R3275	FCC ID: XX6STP9040/XX6STP9240	
	Issue No: 1		
Test No: T5115	Test Photos		Page: 7 of 10




Photograph 11 Radiated Emissions - RSM




Photograph 12 Radiated Emissions - RSM

	Report No: R3275 Issue No: 1	FCC ID: XX6STP9040/XX6STP9240	
	Test No: T5115		Page: 8 of 10




Photograph 13 Radiated Emissions - RSM


	Report No: R3275	FCC ID: XX6STP9040/XX6STP9240	
	Issue No: 1		
	Test No: T5115	Test Photos	Page: 9 of 10



Photograph 14 Radiated Emissions - Car Kit




Photograph 15 Radiated Emissions - Car Kit

	Report No: R3275	FCC ID: XX6STP9040/XX6STP9240	
	Issue No: 1		
	Test No: T5115	Test Photos	Page: 10 of 10



Photograph 16 Radiated Emissions - Car Kit



Photograph 17 Radiated Emissions - Car Kit