


 Test report No.
 FCC_RF_SL17021501-SPC-003_B25 Rev 1.0

 Page
 11 of 50



Note: The spurious emission in different EUT orientation was investigated, including the EUT standing up position and the laying down position. The EUT orientation shown in above setup photo is the worst case position.

775 Montague Expressway, Milpitas, CA 95035, USA • Phone: (+1) 408 526 1188 • Facsimile (+1) 408 526 1088

Т

Visit us at: www.siemic.com; Follow us at: