

American Certification Body  
6731 Whittier Avenue, Suite C110  
McLean, VA 22101  
USA

Ref: Change for FCC ID Y99MC7354 dated October 5, 2015

I would like to have the above mentioned FCC grant exhibits changed. The device does require simultaneous evaluation which was not done for the filing. A revised SAR report has been issued which evaluates the simultaneous requirements of KDB 447498. Further, the correspondence which was loaded indicating the device had redundancy only needs to be removed from the filing.

The product has not been marketed or sold anywhere under this ID.

If you have any questions, please contact me at the below information.

Thank you,



RF Exposure Lab,  
802 N. Twin Oaks Valley Road, Suite 105  
San Marcos, CA 92069  
Ph: (760) 471-2100  
Fax: (760) 471-2121  
Email: [jmmoulton@rfexposurelab.com](mailto:jmmoulton@rfexposurelab.com)