



Date: 10.MAY.2024 02:20:45

Band66_15MHz_QPSK_132597_1RB#0_30~100
0_30~1000




Date: 10.MAY.2024 02:20:54

Band66_15MHz_QPSK_132597_1RB#0_1000~30
00_1000~3000




Date: 10.MAY.2024 02:21:03

Band66_15MHz_QPSK_132597_1RB#0_3000~2
0000_3000~20000




Date: 10.MAY.2024 02:21:13


Band66_15MHz_16QAM_132597_1RB#0_0.009~
0.15_0.009~0.15




Date: 10.MAY.2024 02:21:22




Date: 10.MAY.2024 02:21:31






Date: 10.MAY.2024 02:51:14




Date: 10.MAY.2024 02:51:23

Band66_20MHz_QPSK_132072_1RB#0_30~100
0_30~1000

Band66_20MHz_QPSK_132072_1RB#0_1000~30
00_1000~3000




Date: 10.MAY.2024 02:51:32




Date: 10.MAY.2024 02:51:41

Band66_20MHz_QPSK_132072_1RB#0_3000~2
0000_3000~20000

Band66_20MHz_16QAM_132072_1RB#0_0.009~
0.15_0.009~0.15



Date: 10.MAY.2024 02:51:50



Date: 10.MAY.2024 02:51:59

