


B71\_20M\_QPSK\_1@99\_CH\_133372



B71\_20M\_QPSK\_100@0\_CH\_133372




B71\_20M\_16QAM\_1@99\_CH\_133372



B71\_20M\_16QAM\_100@0\_CH\_133372




B71\_15M\_QPSK\_1@0\_CH\_133197



B71\_15M\_QPSK\_75@0\_CH\_133197



B71\_15M\_16QAM\_1@0\_CH\_133197




B71\_15M\_16QAM\_75@0\_CH\_133197




B71\_15M\_QPSK\_1@74\_CH\_133397




B71\_15M\_QPSK\_75@0\_CH\_133397



B71\_15M\_16QAM\_1@74\_CH\_133397



B71\_15M\_16QAM\_75@0\_CH\_133397




B71\_10M\_QPSK\_1@0\_CH\_133172



B71\_10M\_QPSK\_50@0\_CH\_133172




B71\_10M\_16QAM\_1@0\_CH\_133172



B71\_10M\_16QAM\_50@0\_CH\_133172




B71\_10M\_QPSK\_1@49\_CH\_133422



B71\_10M\_QPSK\_50@0\_CH\_133422




B71\_10M\_16QAM\_1@49\_CH\_133422




B71\_10M\_16QAM\_50@0\_CH\_133422




B71\_5M\_QPSK\_1@0\_CH\_133147




B71\_5M\_QPSK\_25@0\_CH\_133147



B71\_5M\_16QAM\_1@0\_CH\_133147



B71\_5M\_16QAM\_25@0\_CH\_133147




B71\_5M\_QPSK\_1@24\_CH\_133447




B71\_5M\_QPSK\_25@0\_CH\_133447



B71\_5M\_16QAM\_1@24\_CH\_133447



B71\_5M\_16QAM\_25@0\_CH\_133447



## APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

## APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

\*\*\* End of Report \*\*\*

---

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.

---