




NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID5\_N/A  
\_3000\_6000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID5\_N/A  
\_6000\_26000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID5\_N/A  
\_26000\_40000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID18\_N/  
A\_0.009\_0.15\_#1









NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID16\_N/  
A\_0.009\_0.15\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID16\_N/  
A\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID16\_N/  
A\_30\_1000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID16\_N/  
A\_1000\_3000\_#1









NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID17\_NV/  
A\_1000\_3000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID17\_NV/  
A\_3000\_6000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID17\_NV/  
A\_6000\_26000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_M\_TID17\_NV/  
A\_26000\_40000\_#1









NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID6\_N/A  
\_26000\_40000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID4\_N/A  
\_0.009\_0.15\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID4\_N/A  
\_0.15\_30\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID4\_N/A  
\_30\_1000\_#1












NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID5\_N/A  
\_30\_1000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID5\_N/A  
\_1000\_3000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID5\_N/A  
\_3000\_6000\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID5\_N/A  
\_6000\_26000\_#1









NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID18\_N/A\_6000\_26000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID18\_N/A\_26000\_40000\_#1





NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID16\_N/A\_0.009\_0.15\_#1




NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID16\_N/A\_0.15\_30\_#1









NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID17\_N/  
A\_0.15\_30\_#1



NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID17\_N/  
A\_30\_1000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID17\_N/  
A\_1000\_3000\_#1



NTNV\_N77-3450-3550\_PC2\_30\_20\_H\_TID17\_N/  
A\_3000\_6000\_#1

