

---



# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)




# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)



---



# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





---



# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)



---


# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)





# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)



# INTERTEK TESTING SERVICE

---

## Equipment Photographs

Model: DWST08810

(Internal)

