



INTERTEK TESTING SERVICES

Report No. : HK11060734-1  
Sample No. : 1/1



INTERTEK TESTING SERVICES

Report No. : HK11060734-1  
Sample No. : 1/1



Timing Plot – Pursuant to FCC Part 15 Section 15.231 Requirement